Three-phase AC and 3-phase full-wave rectifier output.

The current will go up, because the current requirements will still be the same for the motor. I can barely find anything saying the mathematics of this. Quora is the only place I could find any math remotely similar to what we were looking for, which follows below.

$$2.4 * 20A = 48A$$